BASE BARGE SCHEDULE

DATE 24-Feb-97 - 10:00 AM

EITH 100 Partially discharging (CPLX) at dock. Move to B-1 Wall after partial discharge is complete. Hold at B-1 Wall until further notice.

ETT/112: Loaded (Koch 4) enrouse to dock. ETA dock 1200. Barge will need to be gauged and sampled. Barge will discharge as soon as spotted at dock. Take to W/F after discharge is complete on Low lide 2200 tonight. * Priority 1 / # Priority 1 Brown Water VII will take to Corpus to load (Citgo 4).

ETT[13:3] Empty (Cyclohexane) et Horcules for USCG COI. Brown Canal will take to Corpus after COI has been completed to load (Koch 5).

ETT.1141 Loaded (Citgo 3) enroute to Freeport. ETA 2100. Spot at dock after the ETT 112 has completed * Priority 2 discharging. Barge will need to be gauged and sampled. Will discharge 0730 Tuesday.

ETEXT1555 Empty (NBOL) at W/F. Hold until further moice

CC[7529] Empty (All Oleum) enroute to Rhone-Poulenc.

SCC:108: Empty (All Acks) enroute to Rhone-Poulenc.

SCO 80;88 Loaded (All Oleum) at W/F. Hold until further notice.

SCC 108: Loaded (All Ack) at W/F. Spot at dock after the ETT 110 has completed partially discharging (CPLX) * Priority 3 Barge will discharge 0730 Tuesday.

SCC(104:15 Loading (All Oleum) at Rhone-Poulenc

* - Priority to dock

Friority out to skimmer gate

All priority barges taken to dock should go to skimmer gate as soon as possible after work is complete.

For any further information please contact:

Robert G. Peters

Office: 238-6161

Home: 796~4162

Pager: (713) 604-2418

Suzette Johnson Office: 238-8409

Home: 265-5120

Pager: 237-4016